FIG.1




FIG.2(a)




FIG.2(b)




FIG.2(c)

Ferromagnetic film B	Co-10%Fe(Å) 25	25	25
Ferromagnetic film A	Co-10%Fe(Å) 20	25	28
Measuring magnetic field 1000 Oe	E200-0900.dat 2.5 2 1 0.5 0 -1000 -500 0 500 1000 H(Oe)	E200-0900.dat 2.5 2.5 2.5 2.5 0.5 1.5 0.5 1.5 0.5 1.5 0.5 0	E200-0900.dat 2.5 2.5 2.5 0.5 0.5 0.5 0.5 0.5

FIG.3(a)




FIG.3(b)




FIG.4






FIG.5



First step



Second step

FIG.6(a)




FIG.6(b)




FIG.7




FIG.8




FIG.9




FIG.10




FIG.11




FIG.12




FIG.13




FIG.14





FIG.15






FIG.18




FIG.19




FIG.20

